

RECEIVING INSPECTION REPORT
Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080132-7.3

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 2-9-57

P.O. NO.

VENDOR PACKING SLIP NO.

PLANT #9

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
2	322		61	0	22					
DRAWING NO. AND DESCRIPTION										
732180. Shaft Asbly										
QUANTITY										
ACCEPTED										
REJECTED										
REMARKS										
SHAFTECH #35922										

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11230

RECEIVED FROM

DATE REC'D. 2-9-57

P.O. NO.

VENDOR PACKING SLIP NO.

25-19

Bearing Service Inc., Hayward, California

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
10	322	000000	70	0	22					
DRAWING NO. AND DESCRIPTION										
730170-068 Bearings, Ball, 1/2" x 1/2" x 1/2"										
New Departure										
QUANTITY										
ACCEPTED										
REJECTED										
REMARKS										
10										

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080132-7